

## Aprillia

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
RS125 / Replica	XA	2021-	33-XA-TL01KBA	30 mm	<b>1795</b>
SX125/RX125	KX	2018-	33-KX-TL01KBA	40 mm	<b>1795</b>
Pegaso 650 Strada	VD	2005-	33-VD-TL01KBA	38 mm	<b>1595</b>
Pegaso 650 Trail	VD	2005	33-VD-TL02KBA	40 mm	<b>1795</b>
SX125/RX125	KT	2021-	33-KT-TL01KBA	30 mm	<b>1795</b>
RS 660/Tuono 660	KV/KS	2020-	33-KS-TL01KBA	30 mm	<b>1795</b>
SL750 Shiver	RA	2007-	33-RA-TL01	50 mm	<b>4995</b>
RSV1000 Tuono	RP	2002-	33-RP-TL01KBA	35-40 mm	<b>1595</b>

## BMW

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
G310GS	5G31	2017	33-5G31-TL01KBA	40 mm	<b>1795</b>
G310R	5R31	2016-	33-MG31-TL01KBA	35 mm	<b>1795</b>
G310R	MG31	2021-	33-MG31-TL01KBA	35 mm	<b>1795</b>
G650 XCountry	E65X	2007-08	33-E65X-TL01	70 mm	<b>4995</b>
G650 XCountry	E65X	2009-	33-E65X-TL02	45 mm	<b>4995</b>
G650 Xmoto	E65X	2007-	33-E65X-TL02	65 mm	<b>5695</b>
G650GS	E650G	2011-	33-E650G-TL01KBA	30 mm	<b>2595</b>
F800GS	E8GS	2008-	33-E8GS-TL01	35 mm	<b>4995</b>
F800S	E8ST	2006-	33-E8ST-TL01	45 mm	<b>4995</b>
F800ST	E8ST	2006-	33-E8ST-TL01	45 mm	<b>4995</b>
S1000RR	K10	2009-	33-K10-TL04KBA	31 mm	<b>4995</b>
S1000RR	K10	2012-	33-K10-TL03KBA	30 mm	<b>4995</b>
S1000RR	K10	2015-	33-K10-TL05KBA	25 mm	<b>4995</b>

## Ducati

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
Monster 797	MD	2017-	33-MDDUCATI-TL01KBA	25 mm	<b>1595</b>
Monster 797	ME	2017-	33-MDDUCATI-TL01KBA	25 mm	<b>1595</b>

## Honda

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
CB125F	JC74	2018-	33-JC74-TL01	25 mm	<b>3495</b>
CB125R	JC79	2018-	33-JC79-TL01KBA	32 mm	<b>1795</b>
XL125V Varadero	JC32	2001-	33-JC32-TL01KBA	30 mm	<b>1595</b>
XL125V Varadero	JC49	2011-	33-JC32-TL01KBA	30 mm	<b>1595</b>
CBR250R	MC41	2011-	33-MC41-TL01KBA	20 mm	<b>1595</b>
CBF500	PC39	2004-	33-PC39-TL01KBA	30 mm	<b>1595</b>
CBF500	PC45	2013-	33-PC44-TL01KBA	20 mm	<b>1595</b>
CBF500	PC45	2013-	33-PC44-TL02KBA	40 mm	<b>1595</b>
CB500F/FA/X/XA	PC58/59	2017-	33-PC58-TL01	20 mm	<b>1595</b>

CB500F/FA/X/XA	PC58/59	2017-	33-PC58-TL02KBA	40 mm	<b>1595</b>
CB500X	PC64	2019-	33-PC64-TL01KBA	25 mm	<b>1595</b>
CBR500R	PC44	2013-	33-PC44-TL01KBA	20 mm	<b>1595</b>
CBR500R	PC44	2013-	33-PC44-TL02KBA	40 mm	<b>1595</b>
CBR500R/RA	PC57	2017-	33-PC58-TL01	20 mm	<b>1595</b>
CBR500R/RA	PC57	2017-	33-PC58-TL02KBA	40 mm	<b>1595</b>
CBR500R	PC62	2019-	33-PC63-TL01KBA	25 mm	<b>1595</b>
CB500F	PC63	2019-	33-PC63-TL01KBA	25 mm	<b>1595</b>
CBF500X	PC46	2013-	33-PC44-TL01KBA	20 mm	<b>1595</b>
CBF500X	PC46	2013-	33-PC44-TL02KBA	40 mm	<b>1595</b>
CBF600	PC43	2008-	33-PC43-TL01KBA	20 mm	<b>1595</b>
CBF600S	PC43	2008-	33-PC43-TL01KBA	20 mm	<b>1595</b>
CBR600F	PC41	2011-	33-PC41-TL02	35 mm	<b>4995</b>
CBR600F	PC41	2011-	33-PC41-TL03KBA	30 mm	<b>1595</b>
CBR600RR	PC40	2007-	33-PC40-TL01KBA	30 mm	<b>1995</b>
Hornet 600	PC41	2007-	33-PC41-TL01KBA	25 mm	<b>1595</b>
Hornet 600	PC41	2009-	33-PC41-TL02	35 mm	<b>4995</b>
Hornet 600	PC41	2009-	33-PC41-TL03	30 mm	<b>1595</b>
CB600F Hornet	PC34	1998-	33-PC34-TL01	35-40 mm	<b>6495</b>
CB600F Hornet	PC34	2000-	33-PC34-TL01	35-40 mm	<b>6495</b>
CB600F Hornet	PC36	2002-	33-PC36-TL02	35-40 mm	<b>6495</b>
CBF600	PC38	2005-	33-PC38-TL01KBA	22 mm	<b>1595</b>
CBR600F	PC35	1998-	33-PC35-TL01KBA	35 mm	<b>6495</b>
CBR600F Sport	PC35	2001-	33-PC35-TL01KBA	35 mm	<b>6495</b>
SLR650	RD09	1997-	33-RD09-TL01	30 mm	<b>1995</b>
FMX650	RD12	2005-	33-RD12-TL01KBA	35 mm	<b>1995</b>
CBR650F/A	RC74	2014-	33-RC74-TL01KBA	30 mm	<b>1595</b>
CB650F/A	RC75	2014-	33-RC75-TL01KBA	30 mm	<b>1595</b>
CBR650F/A	RC96	2017-	33-RC96-TL01KBA	25 mm	<b>1595</b>
CB650F/A	RC97	2017-	33-RC96-TL01KBA	25 mm	<b>1595</b>
CB650RA/CBR650R	RH02/RH01	2019-	33-RH02-TL01KBA	30 mm	<b>1795</b>
Integra	RC62	2012-	33-RC62-TL01KBA	30 mm	<b>1595</b>
Integra	RC71	2014-	33-RC71-TL01KBA	30 mm	<b>1595</b>
NC700S	RC61	2012-	33-RC63-TL01KBA	40 mm	<b>1595</b>
NC700X	RC63	2012-	33-RC63-TL01KBA	40 mm	<b>1595</b>
XL700VA Transalp	RD13	2008-	33-RD13-TL01KBA	32 mm	<b>1595</b>
XL700VA Transalp	RD15	2011-	33-RD13-TL01KBA	32 mm	<b>1595</b>
NC750X	RC72	2014-	33-RC72-TL01KBA	40 mm	<b>1595</b>
NC750S	RC70	2014-	33-RC70-TL01KBA	35mm	<b>1595</b>
NC750SD / SA	RC88	2016-	33-RC88-TL01KBA	35mm	<b>1595</b>
Integra NC750D	RC89	2016-	33-RC89-TL01KBA	35mm	<b>1595</b>
NC750XA / XD	RC90	2016-	33-RC90-TL01KBA	35mm	<b>1595</b>
X-ADV	RC95	2017-	33-RC95-TL01KBA	30 mm	<b>1595</b>
Crossrunner	RC60	2011-	33-RC60-TL01KBA	30 mm	<b>1595</b>
VFR800X	RC79	2014-	33-RC79-TL01KBA	30 mm	<b>1995</b>
VFR800X	RC80	2015-	33-RC80-TL01KBA	35mm	<b>1595</b>
CBR900RR	SC33	1996-	33-SC33-TL01KBA	35mm	<b>1795</b>
XL1000V Varadero	SD01	1998-	33-SD01-TL01KBA	40 mm	<b>1595</b>
XL1000V Varadero	SD02	2003-	33-SD02-TL01KBA	40 mm	<b>1595</b>
XL1000V Varadero	SD03	2011-	33-SD02-TL01KBA	40 mm	<b>1595</b>
CRF1000A/L Africa Twin	SD04	2015-	33-SD04-TL01KBA	25 mm	<b>1595</b>
CRF1000A/L Africa Twin	SD06	2017-	33-SD06-TL01KBA	25 mm	<b>1595</b>
CB1000R	SC80	2018-	33-SC80-TL01KBA	25 mm	<b>1595</b>

CBF1000	SC58	2006-	33-SC58-TL01KBA	50 mm	<b>1795</b>
CBF1000F	SC64	2010-	33-SC64-TL01	35 mm	<b>4995</b>
CBR1000RR	SC57	2006-	33-SC57-TL01KBA	30 mm	<b>2595</b>
CBR1000RR	SC59	2008-	33-SC59-TL01KBA	30 mm	<b>1595</b>
VFR1200F	SC63	2010-	33-SC63-TL01KBA	30 mm	<b>1795</b>
Crosstourer	SC70	2012-	33-SC70-TL01KBA	30 mm	<b>1995</b>

## Hyosung

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
GT650iR	GT650	2007-	33-GT650-TL01KBA	35 mm	<b>1595</b>

## Kawasaki

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
Z125	BR125K/L	2018-	33-BR125K-TL01KBA	40 mm	<b>1795</b>
Ninja 125	BX125A/B	2018-	33-BX125A-TL01KBA	35 mm	<b>1795</b>
KLX250	LX250S	2009-	33-LX250S-TL01KBA	40 mm	<b>1595</b>
Ninja 250R	EX250K	2008-	33-EX250K-TL01KBA	33 mm	<b>1595</b>
Ninja 300	EX300A	2012-	33-EX300A-TL01KBA	35 mm	<b>1595</b>
Versys-X 300	LE300C	2017-	33-LE300C-TL01KBA	30 mm	<b>1795</b>
Ninja 400	EX400G	2018-	33-EX400G-TL01KBA	40 mm	<b>1595</b>
Z400	ER400D	2019-	33-ER400D-TL01KBA	30 mm	<b>1595</b>
ER5	ER500A	1997-	33-ER500A-TL01	35 mm	<b>4995</b>
ER5	ER500A	1997-	33-ER500A-TL02	35 mm	<b>4995</b>
ER5	ER500A	2001-	33-ER500A-TL04	35 mm	<b>4995</b>
GPZ500S	EX500D	1994-	33-EX500D-TL01KBA	35 mm	<b>1795</b>
KLE500	LE500A	1991-	33-LE500A-TL01KBA	35 mm	<b>1595</b>
KLE500	LE500A	2001-	33-LE500A-TL02KBA	30 mm	<b>1595</b>
ZX6R	ZX600P	2007-	33-ZX600P-TL01KBA	30 mm	<b>1595</b>
ZX6R	ZX600R	2009-	33-ZX600R-TL01	30 mm	<b>1595</b>
ZX6R	ZX600F	1995-	33-ZX600F-TL01KBA	35 mm	<b>1595</b>
ZX6R	ZX600G	1998-	33-ZX600G-TL01KBA	35 mm	<b>1595</b>
ZX6R	ZX636A	2002-03	33-ZX636A-TL01	30 mm	<b>1595</b>
ZX6R	ZX636B	2003-04	33-ZX636B-TL01KBA	30 mm	<b>1595</b>
ZX6RR	ZX600K	2003-04	33-ZX636B-TL01KBA	30 mm	<b>1595</b>
ZX6R	ZX636C	2005-	33-ZX636C-TL01KBA	30 mm	<b>1595</b>
ZX6R 636	ZX636E	2013-	33-ZX636E-TL01	30mm	<b>1595</b>
ZX6R	ZX636G	2019-	33-ZX636G-TL01KBA	32mm	<b>1795</b>
ER6f	EX650A	2005-	33-ER6-TL01KBA	25 mm	<b>1595</b>
ER6f	EX650C	2009-	33-ER6-TL02KBA	25 mm	<b>1595</b>
ER6f	EX650E	2012-	33-ER6-TL03KBA	25 mm	<b>1595</b>
ER6n	ER650A	2005-	33-ER6-TL01KBA	25 mm	<b>1595</b>
ER6n	ER650C	2009-	33-ER6-TL02KBA	25 mm	<b>1595</b>
ER6n	ER650E	2012-	33-ER6-TL03KBA	25 mm	<b>1595</b>
Z650	ER650H/A2	2017-	33-ER650H-TL01KBA	25 mm	<b>1795</b>
Ninja 650	EX650K/A2	2017-	33-EX650K-TL01KBA	25 mm	<b>1795</b>
Z650 / Ninja 650	EX650M/EX650MA	2020-	33-ER650K-TL01KBA	25 mm	<b>1795</b>
Z650RS	ER650M/A2	2021-	33-ER650M-TL01KBA	25 mm	<b>1795</b>

Versys	LE650A	2006-	33-LE650A-TL02KBA	50 mm	<b>1995</b>
Versys	LE650C	2010-	33-LE650A-TL02KBA	50 mm	<b>1995</b>
Versys 650	LE650E	2015-	33-LE650E-TL01KBA	35mm	<b>2595</b>
Versys 650	LE650E	2017-	33-LE650E-TL01KBA	35mm	<b>2595</b>
Versys 650	LE650EA2	2017-	33-LE650E-TL01KBA	35mm	<b>2595</b>
KLR650 Tengai	KL650C	1995-	33-KL650C-TL01KBA	40 mm	<b>1595</b>
Z750	ZR750L	2007-	33-ZR750L-TL01KBA	30 mm	<b>1795</b>
Z750R	ZR750N	2011-	33-ZR750N-TL01KBA	30 mm	<b>1595</b>
Z750	ZR750J	2003-	33-ZR750J-TL01KBA	30 mm	<b>1795</b>
Z750S	ZR750J	2005-	33-ZR750J-TL02KBA	30 mm	<b>1595</b>
ZR7	ZR750F	1999-00	33-ZR750F-TL01KBA	40 mm	<b>1795</b>
ZR7	ZR750F	2001-	33-ZR750F-TL02KBA	40 mm	<b>1795</b>
Z800	ZR800A	2012-	33-Z800-TL01KBA	35mm	<b>1795</b>
Z800e	ZR800C	2012-	33-Z800-TL01KBA	35mm	<b>1795</b>
Z900/ABS	ZR900B	2017-	33-ZR900B-TL01KBA	30 mm	<b>1795</b>
Z900RS	ZR900C	2018-	33-ZR900C-TL01KBA	40 mm	<b>1795</b>
Z900	ZR900D	2018-	33-ZR900D-TL01KBA	30 mm	<b>1795</b>
Z900	ZR900F	2020-	33-ZR900F-TL01KBA	25 mm	<b>1595</b>
Z900	ZR900F	2020-	33-ZR900F-TL02KBA	40 mm	<b>1995</b>
Z1000	ZRT00B	2007-	33-ZRT00B-TL01KBA	30 mm	<b>1595</b>
KLV1000	WVBS	2002-	33-WVBS-TL01KBA	30 mm	<b>1595</b>
ZX10R	ZXT00C	2004-	33-ZXT00C-TL01	30 mm	<b>1595</b>
ZX10R	ZXT00D	2006-	33-ZXT00D-TL01KBA	30 mm	<b>1595</b>
ZX10R	ZXT00E	2008-	33-ZXT00E-TL01KBA	30 mm	<b>1595</b>
ZX10R	ZXT00F	2010-	33-ZXT00F-TL01KBA	30 mm	<b>1595</b>
ZX10R	ZXT00J	2011-	33-ZXT00J-TL01	30 mm	<b>1995</b>
ZX10R	ZXT00S	2016-	33-ZXT00S-TL01KBA	30 mm	<b>1995</b>
Z1000	ZRT00A	2003-	33-ZRT00A-TL01KBA	30 mm	<b>1595</b>
Versys 1000	LZT00A	2012-	33-LZT00A-TL01KBA	30 mm	<b>1995</b>
Versys 1000	LZT00B	2015-	33-LZT00B-TL01KBA	35 mm	<b>1595</b>
Versys 1000	LZT00C	2019-	33-LZT00C-TL01KBA	35 mm	<b>1795</b>
Z1000	ZRT00D	2010-	33-ZRT00D-TL01KBA	30 mm	<b>1995</b>
Z1000	ZRT00F	2014-	33-ZRT00F-TL01KBA	35 mm	<b>1795</b>
Z1000	ZRT00H	2017-	33-ZRT00H-TL01KBA	35 mm	<b>1795</b>
Z1000	ZRT00H	2017-	33-ZRT00H-TL02	35 mm	<b>1795</b>
Z1000SX	ZXT00G	2011-	33-ZXT00G-TL01KBA	30 mm	<b>1995</b>
Z1000SX	ZXT00L	2014-	33-ZXT00L-TL01KBA	30 mm	<b>1795</b>
Z1000S	ZXT00W	2018-	33-ZXT00W-TL01KBA	25mm	<b>1795</b>
1000SX	ZXT02K	2020-	33-ZXT02K-TL01KBA	30 mm	<b>1595</b>
Z H2	ZRT00K	2020-	33-ZRT00K-TL01KBA	25mm	<b>1595</b>
ZZR1400	ZXT40A	2006-	33-ZXT40A-TL01KBA	30 mm	<b>1795</b>
ZZR1400	ZXT40C	2008-	33-ZXT40C-TL01KBA	30 mm	<b>1795</b>
ZZR1400	ZXT40H	2016-	33-ZXT40H-TL01KBA	30 mm	<b>1795</b>

## KTM

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
125 Duke	KTMISDU KE	2013-	33-KTMISDUKE- TL01KBA	40 mm	<b>1995</b>
125/250/390 Duke	KTMISDU KE	2017-	33-KTMISDUKE- TL05KBA	40 mm	<b>1795</b>
690 SMC R	KTM 690 LC4	2019 -	33-KTM690LC4- TL01KBA	45 mm	<b>1995</b>
790/890 Duke	KTM 790/L	2018-	33-KTM790DUK- TL01KBA	40 mm	<b>1995</b>

## MV Agusta

Modell	Typ	Årsmo <span>del</span>	Art.nummer	Sänkning	Pris
Agusta Brutale 675	B3	2012-	33-B3-TL01KBA	25mm	<b>1595</b>
Agusta Brutale 800	B3	2013-	33-B3-TL02KBA	25mm	<b>1595</b>
Agusta F3 800	F3	2014-	33-F3-TL01KBA	35mm	<b>1595</b>

## Rieju

Modell	Typ	Årsmo <span>del</span>	Art.nummer	Sänkning	Pris
MRT50	MRT3	2018-	33-MRT3-TL01KBA	45mm	<b>1595</b>
RS3 NKD 50	RS33	2018-	33-RS33-TL01KBA	50mm	<b>1595</b>

## Sherco

Modell	Typ	Årsmo <span>del</span>	Art.nummer	Sänkning	Pris
50 SM-R	E50	2018-	33-E50SHERCO-TL01KBA	40mm	<b>1595</b>

## Suzuki

Modell	Typ	Årsmo <span>del</span>	Art.nummer	Sänkning	Pris
DR125SM	CS	2008-	33-CS-TL01KBA	45 mm	<b>1595</b>
GSX-R/S 125	WDL0	2017-	33-WDL0-TL01KBA	30 mm	<b>1995</b>
DRZ400SM	WVB8	2005-	33-WVB8-TL01KBA	45 mm	<b>1595</b>
GS500E	GM51B	1989-	33-GM51B-TL01KBA	40 mm	<b>1595</b>
GS500E	WVBK	2001-	33-WVBK-TL01	30 mm	<b>1595</b>
GS500F	BK	2004-	33-BK-TL01	30 mm	<b>1595</b>
GSR600	WVB9	2006-	33-WVB9-TL01KBA	30 mm	<b>1595</b>
GSXR600	C3	2011-	33-C3-TL01KBA	30 mm	<b>1595</b>
GSXR600	WVCE	2006-	33-WVCE-TL01KBA	35 mm	<b>2595</b>
GSXR600	WVCV	2008-	33-WVCV-TL01KBA	30 mm	<b>2595</b>
GSXR600	AD	1996-	33-AD-TL01	30 mm	<b>1795</b>
GSXR600	WVB2	2004-	33-WVB2-TL01KBA	30 mm	<b>1795</b>
GSXR600	WVBG	2001-	33-WVBG-TL01KBA	35 mm	<b>1795</b>
GSF600 Bandit	GN77B	1995-	33-GN77B-TL01KBA	35 mm	<b>1595</b>
GSF600 Bandit	WVA8	2000-	33-WVA8-TL01KBA	35-40 mm	<b>1595</b>
GSX600F	AJ	1998-	33-AJ-TL03KBA	30 mm	<b>1595</b>
DL650 V-Strom	WVB1	2004-	33-WVB1-TL01KBA	30 mm	<b>1595</b>
DL650 V-Strom	WVB1	2007-	33-WVB1-TL01KBA	30 mm	<b>1595</b>
SV650A	WVBY	2007-	33-WVBY-TL02KBA	28 mm	<b>1595</b>
SFV650 Gladius	WVCX	2009-	33-WVCX-TL01KBA	35 mm	<b>1595</b>
DL650 V-Strom	C7	2011-	33-C7-TL01KBA	45 mm	<b>1595</b>

DL 650/ V-Strom 650/ XT	WC70/71	2017-	33-WC70-TL01KBA	40 mm	<b>1595</b>
SV650	AV	1998-	33-AV-TL01KBA	25 mm	<b>1595</b>
SV650	WVBY	2003	33-WVBY-TL01KBA	25 mm	<b>1595</b>
SV650	WCX0	2016-	33-WCX0-TL01KBA	35 mm	<b>1595</b>
SV650	WCX1	2016-	33-WCX0-TL01KBA	35 mm	<b>1595</b>
Bandit 650A	WVCJ	2007-	33-WVCJ-TL01KBA	35 mm	<b>1595</b>
Bandit 650A	WVCZ	2009-	33-WVCZ-TL01KBA	40 mm	<b>1595</b>
Bandit 650SA	WVCJ	2007	33-WVCJ-TL01KBA	35 mm	<b>1595</b>
GSF650 Bandit	WVB5	2005-	33-WVB5-TL02KBA	35 mm	<b>1595</b>
Bandit 650SA	WVCZ	2009-	33-WVCZ-TL01KBA	40 mm	<b>1595</b>
GSX650F	WVCJ	2008-	33-WVCJ-TL01KBA	35 mm	<b>1595</b>
GSXR750	GR7DB	1996-	33-GR7DB-TL01	37 mm	<b>1795</b>
GSR750	C5	2011-	33-C5-TL01KBA	30 mm	<b>1595</b>
GSXR750	WVB3	2004-05	33-WVB3-TL01KBA	30 mm	<b>1795</b>
GSXR750	WVCF	2006-	33-WVCF-TL01	35 mm	<b>2595</b>
GSXR750	WVCW	2008-	33-WVCW-TL01KBA	30 mm	<b>2595</b>
GSX750F	WVAK	2002-	33-WVAK-TL01	25-30 mm	<b>1595</b>
GSXR750	WVBD	2000-03	33-WVBD-TL01	27 mm	<b>1795</b>
GSXR750	C4	2011-	33-C4-TL01KBA	30 mm	<b>1595</b>
GSX750	AE	1998-	33-AE-TL02	30 mm	<b>4995</b>
GSX750F	AK	1998-	33-AK-TL02	35 mm	<b>1595</b>
GSXS750	WC50	2017-	33-WC50-TL01KBA	30 mm	<b>1595</b>
DL1000 V-Strom	WVBS	2002-	33-WVBS-TL01KBA	30 mm	<b>1595</b>
DL1000 V-Strom	DD	2014-	33-DD-TL01KBA	35 mm	<b>1595</b>
GSX-S1000/F	DG	2015-	33-DG-TL01KBA	40 mm	<b>1795</b>
GSX-S1000S Katana	WDG0	2019-	33-WDG0-TL02KBA	35 mm	<b>1795</b>
GSX-S1000/F	WDG0	2017-	33-WDG0-TL01KBA	40 mm	<b>1795</b>
SV1000	WVBX	2003-	33-WVBX-TL01	37 mm	<b>1795</b>
GSXR1000	WVB6	2005-	33-WVB6-TL01	25 mm	<b>1595</b>
GSXR1000	WVCL	2007-	33-WVCL-TL01	40 mm	<b>2595</b>
GSXR1000	WVCY	2009-	33-WVCY-TL01KBA	30 mm	<b>1595</b>
GSXR1000	WVBZ	2003-04	33-WVBZ-TL01KBA	30 mm	<b>1595</b>
Bandit 1200A	WVCB	2006-	33-WVCB-TL01KBA	37 mm	<b>1595</b>
Bandit 1200SA	WVCB	2006-	33-WVCB-TL01KBA	37 mm	<b>1595</b>
GSF1200 Bandit	GV75A	1996-	33-GV75A-TL01KBA	35 mm	<b>1595</b>
GSF1200 Bandit	WVA9	2001-	33-WVA9-TL01KBA	25 mm	<b>1595</b>
Bandit 1250A	WVCH	2007-	33-WVCH-TL01KBA	38 mm	<b>1595</b>
Bandit 1250SA	WVCH	2007-	33-WVCH-TL01KBA	38 mm	<b>1595</b>
GSX1250FA	WVCH	2010-	33-WVCH-TL01KBA	35 mm	<b>1595</b>
B-King	WVCR	2007-	33-WVCR-TL01KBA	35 mm	<b>1595</b>
VS1400	VX51L	1987-	33-VX51L-TL01	40 mm	<b>4995</b>
VS1400	VX51L	1987-	33-VX51L-TL02	40 mm	<b>4995</b>

## Triumph

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
Daytona 675	D67LC	2006-	33-D67LC-TL01KBA	35 mm	<b>1795</b>
Daytona 675	D67LC	2009-	33-D67LC-TL01KBA	35 mm	<b>1795</b>
Tiger 800	A08	2013-	33-A08-TL01KBA	30 mm	<b>1595</b>
Tiger 800XC	C201	2016-	33-C201-TL01KBA	30 mm	<b>1595</b>
Tiger 1050	115NG	2007-	33-115NG-TL01KBA	30 mm	<b>1595</b>
Tiger Sport 1050	115NG	2014-	33-115NG-TL02KBA	30 mm	<b>1595</b>
Tiger Explorer	V13VG	2014-	33-V13VG-TL01KBA	40 mm	<b>1595</b>

# Yamaha

Modell	Typ	Årsmodell	Art.nummer	Sänkning	Pris
XT125R	74	2005-	33-74-TL01KBA	25 mm	1595
YZF-R125	RE06	2008-	33-RE06-TL01KBA	35 mm	1595
YZF-R125	RE11	2014-	33-RE11-TL03KBA	30 mm	1595
YZF-R125	RE29	2017-	33-RE29-TL01KBA	35 mm	1595
YZF-R125/MT125	RE39	2019- /2020-	33-RE39-TL01KBA	35 mm	1795
XSR125	RE44	2021-	33-RE44-TL01KBA	30 mm	1795
MT-125	RE11	2014-	33-RE11-TL04KBA	30 mm	1595
MT-125	RE29	2017-	33-RE29-TL02KBA	35 mm	1595
DT125R	4BL	1997-	33-4BL-TL01KBA	30-40 mm	1595
DT125R	DE03	1998-	33-DE03-TL01KBA	30 mm	1595
DT125R	DE06	2004-	33-DE06-TL01KBA	50 mm	1595
DT125X	DE06	2004-	33-DE06-TL01	50 mm	1595
WR125R	DE07	2009-	33-DE07-TL01KBA	60 mm	1595
WR125X	DE07	2009-2010	33-DE07-TL02KBA	60 mm	1595
WR125X	DE07	2011-	33-DE07-TL02KBA	50 mm	1595
YZF-R3	RH07	2015-	33-RH07-TL01KBA	25 mm	1595
MT03	RH07	2016-	33-RH07-TL02KBA	25 mm	1595
YZF-R3/A	RH12	2017-	33-RH12-TL01KBA	25 mm	1595
FZ6	RJ14	2007-	33-RJ14-TL01	45 mm	5695
FZ6 Fazer	RJ14	2007-	33-RJ14-TL01	45 mm	5695
FZ6 Fazer S2	RJ14	2007-	33-RJ14-TL01	45 mm	5695
FZS600 Fazer	RJ02	1998-	33-RJ02-TL01KBA	35 mm	1595
YZF600 Thunder Cat	4TV	1996-	33-4TV-TL01KBA	30 mm	1795
YZF600R6	RJ03	1998-	33-RJ03-TL01KBA	35 mm	1595
YZF600R6	RJ05	2003-	33-RJ05-TL01KBA	35 mm	1595
YZF600R6	RJ09	2004-	33-RJ09-TL01KBA	30 mm	1595
YZF600R6	RJ11	2005-	33-RJ11-TL01KBA	37 mm	1995
YZF600R6	RJ15	2008-	33-RJ15-TL01KBA	35 mm	1995
FZ6	RJ07	2003-	33-RJ07-TL02	45 mm	5695
FZ6 Fazer	RJ07	2003-	33-RJ07-TL02	45 mm	5695
XJ6	RJ19	2009-	33-RJ19-TL01KBA	35 mm	1595
XJ6	RJ19	2009-	33-RJ19-TL01KBA	35 mm	1595
XJ6 Diversion	RJ19	2009-	33-RJ19-TL01KBA	35 mm	1595
XJ6	RJ22	2013-	33-RJ22-TL01KBA	30 mm	1595
XJ6 Diversion	RJ22	2013-	33-RJ22-TL01KBA	30 mm	1595
YZF-R6	RJ27	2017-	33-RJ27-TL01KBA	35 mm	2595
XJ600N	4BR	1991-96	33-4BR-TL01KBA	30 mm	2595
XJ600N	4BR	1997-	33-4BR-TL02	30 mm	2595
XJ600N	4BRA	1991-96	33-4BR-TL01KBA	30 mm	2595
XJ600N	4BRA	1997-	33-4BR-TL02	30 mm	2595
XJ600N	4BRB	1991-96	33-4BR-TL01KBA	30 mm	2595
XJ600N	4LX	1993-96	33-4BR-TL01KBA	30 mm	2595
XJ600N	4LX	1997-	33-4BR-TL02	30 mm	2595
XJ600N	RJ01	1998-	33-RJ01-TL01KBA	35 mm	2595
XJ600S	4BR	1991-96	33-4BR-TL01KBA	30 mm	2595
XJ600S	4BR	1997-	33-4BR-TL02	30 mm	2595
XJ600S	4BRA	1991-96	33-4BR-TL01KBA	30 mm	2595
XJ600S	4BRA	1997-	33-4BR-TL02	30 mm	2595
XJ600S	4BRB	1991-96	33-4BR-TL01KBA	30 mm	2595
XJ600S	4LX	1993-96	33-4BR-TL01KBA	30 mm	2595
XJ600S	4LX	1997-	33-4BR-TL02	30 mm	2595
XJ600S	RJ01	1998-	33-RJ01-TL01KBA	35 mm	2595

XT600E	3TB	1990-	33-XT600-TL01KBA	35 mm	<b>2595</b>
XT600E	3UW	1990-	33-XT600-TL01KBA	35 mm	<b>2595</b>
XT600E	DJ02	1998-	33-XT600-TL01KBA	35 mm	<b>2595</b>
XT600K	3TB	1990-	33-XT600-TL01KBA	35 mm	<b>2595</b>
XT600K	3UW	1990-	33-XT600-TL01KBA	35 mm	<b>2595</b>
XT600K	DJ02	1998-	33-XT600-TL01KBA	35 mm	<b>2595</b>
MT03	RM02	2006-	33-RM02-TL01KBA	30mm	<b>1795</b>
XT660R	DM01	2004-	33-DM01-TL01KBA	40 mm	<b>1595</b>
XT660X	DM01	2004-	33-DM01-TL02KBA	50 mm	<b>1595</b>
XT660Z Tenere	DM02	2008-	33-DM02-TL01KBA	50 mm	<b>1595</b>
XT660Z Tenere	DM04	2013-	33-DM04-TL01	40 mm	<b>1595</b>
R7	RM39/40	2021-	33-RM39-TL01KBA	40 mm	<b>1795</b>
Ténéré 700	DM07/DM08	2019-	33-DM07-TL03KBA	20 mm	<b>1595</b>
Tracer 700	RM30/31	2020-	33-RM30-TL01KBA	40 mm	<b>1995</b>
MT07	RM04	2014-	33-RM04-TL01KBA	45mm	<b>1995</b>
MT07 Tracer	RM14/15	2016-	33-RM14-TL01KBA	40 mm	<b>1995</b>
MTT 690 / Tracer 700	RM14/15	2016-	33-RM14-TL01KBA	40 mm	<b>1995</b>
MT07/A/Moto-Cage	RM17/18	2017-	33-RM17-TL01KBA	45mm	<b>1995</b>
MT07/A/MTN690/A/U	RM17/18	2018-	33-RM17-TL02KBA	40 mm	<b>1995</b>
MT07	RM33/34	2021-	33-RM33-TL01KBA	40 mm	<b>1995</b>
XSR700	RM11/12	2016-	33-RM11-TL01KBA	35 mm	<b>1995</b>
XSR700	RM36/37	2021-	33-RM36-TL01KBA	40 mm	<b>1995</b>
XV750	4FY	1992-	33-4FY-TL02	50 mm	<b>4995</b>
YZF750R	4HN	1993-	33-4HN-TL01	30 mm	<b>1795</b>
Fazer 8	RN25	2010-	33-RN25-TL01KBA	30 mm	<b>1995</b>
FZ8	RN25	2010-	33-RN25-TL01KBA	30 mm	<b>1995</b>
MT-09 / ABS	RN29	2013-	33-RN29-TL01KBA	25 mm	<b>1595</b>
MT-09 / ABS	RN29	2015-	33-RN29-TL02KBA	25 mm	<b>1595</b>
XSR900/MTM850	RN43	2016-	33-RN43-TL03KBA	25 mm	<b>1595</b>
MT09 ABS / MTN850 A	RN43	2017-	33-RN43-TL04KBA	25 mm	<b>1595</b>
Tracer 900	RN43	2017-	33-RN43-TL05KBA	30 mm	<b>1595</b>
MT09 / SP	RN69	2021-	33-RN69-TL01KBA	35 mm	<b>1595</b>
Tracer 9 / GT	RN70	2021-	33-RN70-TL01KBA	30 mm	<b>1595</b>
Tracer 900/GT	RN57	2018-	33-RN57-TL01KBA	30 mm	<b>1595</b>
TRX850	4UN	1996-	33-4UN-TL01KBA	35 mm	<b>1595</b>
XJ900	4KM	1994-	33-4KM-TL01KBA	40 mm	<b>1595</b>
TDM900	RN08	2002-	33-RN08-TL01KBA	35 mm	<b>1595</b>
TDM900	RN11	2004-	33-RN11-TL01	30 mm	<b>1595</b>
TDM900	RN18	2006-	33-RN18-TL01	30 mm	<b>1595</b>
MT-10/ MTN1000	RN45	2016-	33-RN45-TL01KBA	30 mm	<b>1795</b>
FZ1	RN16	2006-	33-RN16-TL01KBA	30mm	<b>1995</b>
FZ1 Fazer	RN16	2006-	33-RN16-TL01KBA	30mm	<b>1995</b>
FZS1000 Fazer	RN06	2001-	33-RN06-TL01	19 mm	<b>1595</b>
FZS1000 Fazer	RN14	2005-	33-RN14-TL01	30mm	<b>1595</b>
YZF1000R1	RN01	1998-	33-RN01-TL01KBA	30 mm	<b>1795</b>
YZF1000R1	RN04	2001-	33-RN04-TL01KBA	30 mm	<b>1795</b>
YZF1000R1	RN09	2002-	33-RN09-TL01KBA	25-30 mm	<b>1795</b>
YZF1000R1	RN12	2004-06	33-RN12-TL01KBA	30 mm	<b>1795</b>
YZF1000R1	RN19	2007-	33-RN19-TL01KBA	25 mm	<b>1795</b>
YZF1000R1	RN22	2009-	33-RN22-TL01KBA	25 mm	<b>1795</b>
YZF-R1 ABS	RN32	2015-	33-RN32-TL01KBA	30mm	<b>2595</b>
YZF-R1	RN49	2017-	33-RN49-TL01KBA	30mm	<b>2595</b>



YZF-R1	RN65	2020-	33-RN65-TL01KBA	30mm	<b>1995</b>
BT1100 Bulldog	RP05	2001-	33-RP05-TL01KBA	35 mm	<b>1595</b>
XV1100 Virago	3LP	1989-	33-3LP-TL02	50 mm	<b>5295</b>
XT1200Z Super Tenere	DP07	2017-	33-DP07-TL01	40 mm	<b>1595</b>
FJR1300	RP08	2003-	33-RP08-TL01KBA	25 mm	<b>1595</b>
FJR1300	RP11	2004-	33-RP11-TL01KBA	25 mm	<b>1595</b>
FJR1300A	RP13	2006-	33-RP13-TL01KBA	30 mm	<b>1595</b>

**Vi reserverar oss för eventuella tryckfel!**